

GUN # A-30

SERIAL # 71148876

CAL: 300 WIN MAG

M710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW 1303A		
JS	12-22-03	Detonate - Scope Crosshair	Front 40 Rear 40		
BL	12-22-03	Headspace	Min + .003		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min + .003		
JS/BL	12-22-03	Depth Front Take down	Screw hole		
BL	12-28-03	firing Pin Indents	.018 - .007 - .009 Avg. .0186		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0298		
JS	12-29-03	Gear Lift	.0154		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Headspace	Min + .004		
SW/JS	1/13/04	Proof Rel		1	2
SW/JS	1/13/04	Headspace after proof	Min + .004		
SW	1/15/04	300 Rd Basic Jth Function Test		200	202
SW	1-15-04	Headspace Min + .004	(Center Take down screw loose)		
BL	1-16-04	Shoulder Fire	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

BARBER - 5.22.06-0003647

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-30

TLW #: TLW1303

Date: 01 / 20 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min t. 004☒ Sear Engagement: 1st. 0292 2nd. 0279 3rd. 0277Ave. 0282 spec. .020" to .025"☒ Trigger Pull: 1st. 4.801 2nd. 4.858 3rd. 4.733Ave. 4.791 spec- 4 lbs. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Some wear on bolt face☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs some wear Bolt stop worn☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box protruding

TLW1303

Remington Confidential

ET20027