

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-2

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min + .005☐ Sear Engagement: 1st. 2nd. 3rd. Ave. spec- .020" to .025"☐ Trigger Pull: 1st. 2nd. 3rd. Ave. spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary. Take down screws loose Top☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs some wear, Bolt Stop some wear☐ Inspect stock for any signs of cracking or other
failure. ☒ Other items ofnote: magazine Box Protruding, insert has a defect must be in the mold.Couldn't do engagement or trigger, Mike Kenney took bolt head to get evaluated

TLW1303

Remington Confidential

ET20111