

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-10

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min+.001☒ Sear Engagement: 1st. .028 2nd. .026 3rd. .026Ave. .0268 spec- .020" to .025"☒ Trigger Pull: 1st. 4.62 2nd. 4.63 3rd. 4.68Ave. 4.649 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Bolt stop excessive wear Locking lugs some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine box is protruding, receiver insert has a defect must be in mold.

TLW1303

Remington Confidential

ET20127