

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	
				AT START-0 RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Detorque Scope Cross Bolt Screws	Front 35 Rear 30		
BL		Head space	min +.004		
BL		Proof	OK	1	1
BL	12/22/03	Head space	min +.004		
JS/BL	12/22/03	Depth Front Take down Screws hole			
BL	12/23/03	Firing Pin Indent	.022-.022-.020 Avg. .0213		
JS	12-29-03	Seat/Trigger Engagement	Arg. .0261		
JS	12-29-03	Scar lift	.0159		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min +.005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min +.005		
SW	1/15/04	200 Rd Basic Jack Function Test		200	202
SW	1-15-04	Head space Min +.005			
BL	1-16-04	Shoulder Fine	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

BARBER - 5.22.06r0003779

4

Confidential - SUPERSEDED BY ORDER 1005779

ET20158

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-27

TLW #: TLW1303

Date: 01/20/04Inspector: JS/BLRound Level: 222
☒ Measure Headspace min 0.005
☒ Sear Engagement: 1st 0.025 2nd 0.055 3rd 0.0247
Ave. 0.025 spec- 0.020" to 0.025" 83
☒ Trigger Pull: 1st 4.269 2nd 4.471 3rd 4.298
Ave. 4.346 spec- 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs same as before
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of
note: magazine Box protruding

TLW1303

Remington Confidential

ET20159