

CAL: 300 WIN MAG

M710 MAGNUM TRIAL AND PILOT TEST 1.1

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	Indents			
SW / BL	2/17/04	SEAL LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW / BL	2/17/04	TRIGGER PULL			
JS	2/19/04	200 Rd Jack Funct.		200	201
BL	2/27/04	500 Rd Ext. Endur Test		500	701
BL	3/8/04	Clean/Inspection	see Inspection Sheet		
BL	3/9/04	Clean/Inspection	see Inspection Sheet		

Logform

BARBER - 5.22.06r0004108

CONFIDENTIAL - SUBPOENA 502-PR-00064108 Order

ET21108

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-21

TLW #: TLW1303

Date: 3 / 9 / 04

Inspector: DL

Round Level: 201

- ☐ Measure Headspace min f-005.
- ☒ Inspect Take Down Screws for loosening. Center screw 1/2 turn - Top screw 1/2 turn
- ☒ Sear Engagement: 1st. .0334 2nd. .0347 3rd. .0342 Ave. .0341 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0273 2nd. .0283 3rd. .0288 Ave. .02813
- ☒ Trigger Pull: 1st. 5.225 2nd. 5.210 3rd. 5.172 Ave. 5.202 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking lugs some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure. cracked Stock at center screw hole
- ☐ Other items of note:

TLW1216

Remington Confidential

ET21109

CAL: 300 WIN MAG

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW / SW / BL	2/16/04	INDENTS			
SW / BL	2/17/04	SEAR LIFT	SEE DATA SHEET		
SW / BL	2/17/04	ENGAGEMENT			
SW / BL	2/17/04	TRIGGER PULL			
JS	2/19/04	200 Rd Jack Funct.			
BL	2/27/04	500 Rd Ext. Endur Test		200	201
BL	3/9/04	Clean / Inspection	See Inspection Sheet	500	701

Logform

50

BARBER - 5.22.06r0004110

ET21110

Confidential - ~~BAKER-2022-06060410~~ Order
Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A22

TLW #: TLW1303

Date: 3 / 9 / 04Inspector: BLRound Level: 701

- ☒ Measure Headspace min +.005
- ☒ Inspect Take Down Screws for loosening. Top screw 1/4 turn - Center screw 1/8 turn 83
- ☒ Sear Engagement: 1st. .0299 2nd. .0291 3rd. .0301 Ave. .0297 spec-.025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. .0299 2nd. .0299 3rd. .0299 Ave. .0299
- ☒ Trigger Pull: 1st. 4.728 2nd. 4.839 3rd. 4.608 Ave. 4.725 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 4.728 2nd. 4.839 3rd. 4.608 Ave. 4.725
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, ~~bolt~~ Bolt Stop some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure. cracked stock at center screw hole
- ☐ Other items of note: _____
- _____
- _____
- _____

TLW1216

Remington Confidential

ET21111