

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A75

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BL

Round Level: _____

☒ Measure Headspace min + .007☒ Sear Engagement: 1st. 0.282 2nd. 0.265 3rd. 0.275Ave. 0.274 spec- .020" to .025"☒ Trigger Pull: 1st. 4.139 2nd. 3.984 3rd. 3.736Ave. 3.963 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. Broken extractor☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: BOLT STOP some wear, locking lugs some wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine Box is protruding - receiver 1 sent has a defect must be in the mold.

TLW1303

Remington Confidential

ET21299