

GUN # A-18

M710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

SERIAL # 71147113

PROJECT # 241314

CAL: 300 WIN MAG

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque-Scope Crosshair Screws Front Rear			
BL	12-22-03	Headspace min +.005			
BL	12-22-03	Proof Ok		1	1
BL	12-22-03	Headspace min +.005			
JS/BL	12-22-03	Depth Front Take down screw hole			
BL	12-23-03	Firing Pin Indents .021-.022-.022 Avg .0216			
JS	12-29-03	Seal/Trigger Engagement Avg. .0274			
JS	12-29-03	Seal lift .0145			
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006			
SW/JS	1/13/04	Proof Rd		1	0
SW/JS	1/13/04	Headspace after proof Min +.006			
JS	1-15-04	200 Rd. Jack function test Bolt difficult to close throughout test, Rds 141-160 were difficult to chamber (soft point of round was flattening out from recoil Flat end of primer was difficult to slide over lip of magazine.) Front & Center Takedown screws backed out, then were removed and reinserted & torqued.		200	202
SW	1-15-04	Headspace Min +.007			
		Bolt hard to close / Bolt not functioning properly			
JS/BL	1-20-04	Clean/Inspect see Inspection sheet Broken extractor		20	222

Logform

BARBER - 5.22.06/0004313

Confidential - SBARBER - 5.22.06/0004313 Order

Williams V. Remington

ET21313