

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-18

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 022
☒ Measure Headspace min + .006
☒ Sear Engagement: 1st. 0288 2nd. 0278 3rd. 026
Ave. 0275 spec- .020" to .025" Reset to Eng. 0241
☒ Trigger Pull: 1st. 5.070 2nd. 4.700 3rd. 4.879
Ave. 4.883 spec- 4 lb. to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor
☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop some wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding - receiver insert has defect must be fixed.

TLW1303

Remington Confidential

ET21314