

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/14/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate Scope Crossbolt Screws	Front 30 Rear 32		
BL	12-22-03	Headspace	Min + .005		
BL	12-22-03	Proof	Tight to open	1	1
BL	12-22-03	Headspace	Min + .005		
JS/BL	12-22-03	Depth Front Takedown Screw hole			
BL	12-23-03	Firing Pin Indents	.022 - .021 - .021 Avg .0213		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0272		
JS	12-29-03	Sear lift	.0148		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min + .006			
SW/JS	1/13/04	Proof RD		1	2
SW/JS	1/13/04	Headspace after proof	Min + .006		
JS	1-15-04	200 Rd. Jack & function test	Bolt difficult to close on Rds. 81-100; 121-140; 161-180	200	202
SW	1-15-04	Headspace Min + .006	(Center Takedown screw loose)		
BL	1-16-04	Shoulder Fine	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet - Broken extractor		

Logform

ET21318