

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	De-torque Scope Cross Bolt Screws	front 25 Rear 20		
BL		Head space	Min + .002		
BL		Proof	OK.	1	1
BL	12/22/03	Head space	Min + .004		
JS/BL	12/22/03	Depth Front Take down screw hole			
BL	12/23/03	Firing Pin Indents	.027 - .028 - .019 Avg .020		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0288		
JS	12-29-03	Sear lift	.0168		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min + .003		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min + .004		
Bee	1/15/04	Load Jack Pin test	Bolt hard to close / magazine box hard to take from magazine well	200	202
SW	1-15-04	Head space	Min + .005 (Front Take down & Center screw loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

ET21348