

GUN # A-26
SHOOTER: SW
SERIAL # 71148863
CAL :300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314

AMMO :		DATE : 1/18/04	ROUND LEVEL - 0
MALFUNCTIONS		MALFUNCTIONS	
LOT #			
1 Rem RS300WA Lot# R16E133523	51		
2 HTC	52		
3	53		
✓ 4	54		
5 Bolt came out (Bolt Latch Failed)	55		
6	56		
7	57		
8 Bolt came out	58		
9	59		
10 HTC	60		
11	61	Rem PR C300WC Lot# W10BB1	
✓ 12	62		
13	63		
14	64		
15	65		
✓ 16 Bolt came out	66		
17	67		
18	68		
19	69		
✓ 20	70		
21 Rem PR SC300WB Lot# T25BD1	71		
22	72		
23	73		
24	74		
25	75		
26 Bolt came out HTC	76		
27	77		
28	78		
29	79		
30 HTC	80		
31	81	Rem A300W2 Lot# W27PB1	
32	82		
33	83		
34	84		
35	85		
36	86		
37	87		
38 Bolt came out HTC	88		
39	89		
✓ 40	90		
41 Rem A300W1 Lot# T05EB1	91		
42 Bolt Latch Failed HTC	92		
43	93		
44 Bolt Latch Failed HTC	94		
45	95		
46 Bolt Latch Failed HTC	96		
47	97		
✓ 48	98	Bolt Latch Failed	
49	99		
50	100		

Front of Magazine bends out makes hard to
get magazine in or out. 100
7 - Bolt hard to cycle over first round from magazine
13 - Bolt Latch Failed (bolt came out when cycled)

ET21355

GUN # 100
SHOOTER: SW
SERIAL #
CAL :300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

FEW1503
PROJECT # 241314

AMMO :		DATE : 1/15/04		ROUND LEVEL - 100	
MALFUNCTIONS		MALFUNCTIONS			
LOT #					
1	Rem PRA 300 WC Lot# U291A1	51			
2		52			
3		53			
4		54			
5		55			
6	Bolt Latch Failed	56			
7		57			
8		58			
9		59			
10		60	✓		
11		61	Fed 300 WGS Lot# 304 J153		
12		62	Rem		
13		63			
14		64			
15		65			
16		66			
17		67			
18		68			
19		69			
20	✓	70	Bolt Latch Failed		
21	Win SHV30WM2 Lot# RNO2	71			
22	Bolt Latch Failed	72			
23		73			
24		74			
25		75			
26		76			
27		77			
28		78	Bolt Latch Failed		
29		79			
30		80	✓		
31		81	Fed P300WC Lot# 304 J030		
32		82	Bolt Latch Failed		
33		83			
34		84			
35		85			
36		86			
37		87			
38		88			
39		89			
40	✓	90			
41	Win X30WM2 Lot# 4TL20	91			
42		92			
43		93			
44		94			
45		95			
46		96			
47		97			
48		98			
49		99			
50		100	✓		

000

ET21356