

GUN # A-28
 SHOOTER: SJ
 SERIAL # 71148866
 CAL : 300 WIN MAG

200 RD BASIC JACK FUNCTION TEST

TLW1303
 PROJECT # 241314

AMMO :		DATE : 1/15/04 ROUND LEVEL - 0	
MALFUNCTIONS		MALFUNCTIONS	
LOT #			
1 Rem A300WA Lot# R16EB3523	51		
2	52		
3	53		
4	54		
5	55		
6	56		
7	57		
8	58		
9	59		
10	60		
11	61	Rem PRC300WC Lot# U10B01	
12	62		
13	63		
14	64		
15	65		
16	66		
17	67		
18	68		
19	69		
20	70		
21 Rem PRC300WB Lot# T250B1	71		
22	72		
23	73		
24	74		
25 HTC	75		
26	76		
27	77		
28	78		
29	79		
30	80		
31	81	Rem A300W2 Lot# U27P01	
32	82		
33	83		
34 HTC	84		
35	85		
36	86		
37	87		
38	88		
39	89		
40	90		
41 Rem A300W1 Lot# T05E01	91		
42 Bolt Latch Failed HTC	92		
43	93		
44	94		
45	95		
46	96		
47	97		
48	98		
49	99		
50	100		

Front of Magazine bends out make hard to
 set magazine in or out.
 3 - Bolt hard to cycle over first round from magazine
 1 - Bolt Latch Failed (bolt came out when cycled)

100

ET21365

GUN # A-28
SHOOTER: SW

200 RD BASIC JACK FUNCTION TEST

TLW1303
PROJECT # 241314SERIAL #
CAL :300 WIN MAG

AMMO :		DATE: 1/15/04 ROUND LEVEL - 100	
LOT #	MALFUNCTIONS		MALFUNCTIONS
1	Rem PRA300WC Lot # u39IA1	51	
2		52	
3		53	
4		54	
5		55	
6		56	
7		57	
8		58	
9		59	
10		60	
11		61	Fed 300 WGS Lot # 3043153
12		62	
13		63	
14		64	
15		65	
16		66	
17		67	
18		68	
19		69	
20		70	
21	Win SHV30WM2 Lot # RND2	71	
22		72	
23		73	
24		74	
25		75	
26		76	
27		77	
28		78	
29		79	
30		80	
31		81	Fed P300WC Lot # 3043030
32		82	
33		83	
34		84	
35		85	
36		86	
37		87	
38		88	
39		89	
40		90	
41	Win X30WM2 Lot # 4TL20	91	
42		92	
43		93	
44		94	
45		95	
46		96	
47		97	
48		98	
49		99	
50		100	

300

ET21366