

TRACKING #TLW1447
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
SW/JS	4/23/04	Head space	Min +.002	TLW1447A	
"	"	Head space	Bolt Type GO won't close	"	
SW/JS	4/28/04	Proof Rd	OK Hammer bolt back	TLW1447B	1
"	4/26/04	Head space	Min +.003		
"	"	Head space	Bolt Type GO won't close		
SW	4/26/04	Firing Pin Indent	.018, .018, .017 Avg. .0176	TLW1447D	
JS	4/28/04	Accuracy	3 groups of 5 shots 5 Fouling shots	TLW1447T	20
B Lee	5-4-04	Safe on/off Forces	See Inspection sheet	TLW1447G	21
B. Lee	5-4-04	Bolt Lift / Force	"	TLW 1447 H	
B. Lee	5-4-04	Bore diameter	"	TLW 1447 L	
B. Lee	5-4-04	Twist Rate	"	TLW1447N	
SW/BL	5-6-04	Engagement		TLW1447E	
"	"	Trigger Pull		TLW1447F	
"	"	4.915 4.942	5.084 4.951 4.915 Avg. 4.961		
"	"	Reset Engagement	.0252, .0285, .0282 Avg. .02533	TLW1447X	
"	"	Reset Trigger Pull		TLW1447X	
"	"	4.474, 4.467, 4.516, 4.520, 4.673	Avg 4.530		
"	5-7-04	Saami Jar-off	PASS	TLW1447K	
"	"	Rotation Test	PASS	TLW1447Y	
SW	5-7-04	middle screw stripped / replace	From Gun A-1		
SW/BL	5/7/04	Saami Drop	PASS	TLW1447W	
SW/BL	5/10/04	"	checked insert (Broken Pictures taken)		

THIS SHEET IS TO ACCOMPANY THE FIREARM AT ALL TIMES THROUGHOUT TESTING

FORMS.XLS

BARBER - 5.22.06r0004545

9.

Confidential - Subpoena Order
- 5.2.2.061004545
- 5.2.2.061004545

ET21545