CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"					
	Project: 241314		TLW #: TLW168	9	
	Date: 2. /	25.105			
	Gun Test # <i>A 2</i>	23	S/N 7/2031	90	
	Round Level:	721	Inspector: B. C	<u>LEE</u>	. 3 83
a ′	Measure Headspace	5	2 (A)		
a	Check Takedown Screw Torque @ Dis	assembly: Frt /Ô	_, Center /0	_, Rear	
	Scar Engagement: 1st 278 2nd.	028 3rd. 10302	Ave. 02.55	spec025" to.0	30"
	Reset Sear Engagement if Required: 1	st 2 nd .	3rd	Ave	
'	Trigger Pull: 1st. 4.668 2.4.5	77 3 rd . 4.592	Ave. 4.612	spec- 4.5 lb. to 6 lb	•
	Reset Trigger Pull if Required 1st	2 nd 3 rd .	<u></u>	Ave	
Q.	-Inspect Firecontrol Insent for any sign	ns of cracking or other			,
	failure.				
,			·		•
	Other items of			•	
100,000	note:				
		•			
a	Torque Takedown Screws @ Reassemb	oly: SPEC- Frt- 75 in lb	s, Center- 30-35 in I	bs, Rear- 15 in lbs.	
					TLW1216
					12.11210
			*		
	Re	emington Confid	lential	· 6	
	· · ·				

ET21860