

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 12 105

Gun Test # A-21

S/N 71202765

Round Level: 2231

Inspector: B. Lee

- ☒ Measure Headspace min^t. 005.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 45, Center 30, Rear 15
- ☒ Sear Engagement: 1st. .025 2nd. .025 3rd. .025 Ave. .0257 spec-.025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave.
- ☒ Trigger Pull: 1st. 4.534 2nd. 4.222 3rd. 4.203 Ave. 4.320 spec- 4.5 lb. to 6 lb.
- ☒ Reset Trigger Pull if Required: 1st. 5.169 2nd. 5.150 3rd. 5.242 Ave. 5.187
- ☒ Inspect Firecontrol Inset for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21887