

CONFIDENTIAL

Remington Arms Company Inc.
 Research & Development Technical Center
 315 West Ring Road
 Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 1 22 105

Gun Test # 4-33

S/N 71203001

Round Level: 719

Inspector: BLEE

- ☒ Measure Headspace min⁺.005.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 10, Center 20, Rear 15.
- ☒ Sear Engagement: 1st. .6275 2nd. .0276 3rd. .0288 Ave. .6275 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. 2nd 3rd. Ave.
- ☒ Trigger Pull: 1st. 5.915 2nd. 6.085 3rd. 5.956 Ave. spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd 3rd. Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21976