

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 / 24 / 05

Gun Test # A-31

S/N 71202744

Round Level: 1229

Inspector: B-LEE

- ☒ Measure Headspace min +.006
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 30, Center 20, Rear 15
- ☒ Sear Engagement: 1st .0305 2nd .0301 3rd .0301 Ave. .0302 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 4.632 2nd 4.659 3rd 4.764 Ave. 4.685 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22035