

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

### Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 12 1 05

Gun Test # A-11

S/N 71202772

Round Level: 2211

Inspector: B. Lee

- Measure Headspace min<sup>+</sup>.003
- Check Takedown Screw Torque @ Disassembly: Frt 40, Center 35, Rear 10
- Sear Engagement: 1<sup>st</sup>. .0242 2<sup>nd</sup>. .0238 3<sup>rd</sup>. .0238 Ave. .0239 spec-.020" to .025"
- Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- Trigger Pull: 1<sup>st</sup>. 3.791 2<sup>nd</sup>. 3.770 3<sup>rd</sup>. 3.685 Ave. 3.755 spec- 4 lb. to 5.5 lb.
- Reset Trigger Pull if Required: 1<sup>st</sup>. 4.513 2<sup>nd</sup>. 4.455 3<sup>rd</sup>. 4.418 Ave. 4.462
- Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- Other items of note: \_\_\_\_\_
- Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential