

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 122105

Gun Test # A-12

S/N 71202769

Round Level: 701

Inspector: BLCE

- ☒ Measure Headspace min .001.
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 25, Center 25, Rear 15.
- ☒ Sear Engagement: 1st .0244 2nd .0249 3rd .0252 Ave. .0248 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 5.54 2nd 5.509 3rd 5.550 Ave. 5.542 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note: _____
- ☒ Torque Takedown Screws @ Reassembly: SPEC: Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22079