

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"

Project: 241314

TLW #: TLW1689

Date: 3 1 2 1 05Gun Test # A 1S/N 71202770Round Level: 2211Inspector: B. LEE

- ☒ Measure Headspace min: .004
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 20, Center 30, Rear 10
- ☒ Sear Engagement: 1st .0257 2nd .0253 3rd .0257 Ave. .0256 spec-.020" to .025"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 3.9622 2nd 4.078 3rd 4.038 Ave. 4.026 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. OK
- ☐ Other items of note:
- ☒ Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET22190