

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-8

TLW #: TLW1216

Date: 8 / 20 / 03Inspector: SW/BLRound Level: 221☒ Measure Headspace min+.002☒ Sear Engagement: 1st. .0279 2nd. .0279 3rd. .0279 Ave. .0279 spec. .020" to .025"☒ Reset Sear Engagement if Required: 1st. .0232 2nd. .0231 3rd. .0231 Ave. .02313☒ Trigger Pull: 1st. 4.399 2nd. 4.518 3rd. 4.503 Ave. 4.473 spec. 4 lb. to 5.5 lb.☒ Reset Trigger Pull if Required: 1st. 4.326 2nd. 4.215 3rd. 4.344 Ave. 4.295☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: _____☒ Inspect stock for any signs of cracking or other

failure. Lower corners of recoil bracket has cracks on stock
Crack on middle take down screw hole

☒ Other items of

note: Top of magazine Box has some protrusion, wear in
magazine latch area

TLW1216

Remington Confidential

ET22359