

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-6

TLW #: TLW1216

Date: 9 / 10 / 03Inspector: SW/BLRound Level: 1141

- ☒ Measure Headspace Min +.007
- ☒ Sear Engagement: 1st. .0243 2nd. .0242 3rd. .0245 Ave. .0243 spec- .020" to .025"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 5.080 2nd. 4.960 3rd. 4.998 Ave. 5.013 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Normal wear wear on bolt stop
- ☒ Inspect stock for any signs of cracking or other failure. Cracks in stock
- ☒ Other items of note: Top of magazine box has some protrusion wear in magazine latch area - Extractor inside bolt head not extracting properly

TLW1216

Remington Confidential

ET22439