

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-10

TLW #: TLW1530

Date: 8 / 16 / 04Inspector: SWRound Level: 241
☒ Measure Headspace Min +.003
☒ Sear Engagement: 1st .0355 2nd .0355 3rd .0353
Ave. .03543 spec. .020" to .025"
☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____

Ave. _____

☒ Trigger Pull: 1st 4.191 2nd 4.196 3rd 4.224
Ave. 4.204 spec. 4 lb. to 5.5 lb.
☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____

Ave. _____

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear
☒ Inspect stock for any signs of cracking or other failure. OK
☒ Other items of note: _____

TLW1216

Remington Confidential

ET22926