

K. J. LOWE

- 2 -

September 16, 1941

Front

Swivel - The counterbore in the stock to receive this swivel appears too deep. The swivel base mars the stock.

One or two other minor points will be discussed with you by Trigg Stewart. Please correct these points and re-submit the production sample and model gun for Products Committee action.

---

Development Division

HAB:HEP

CMM