

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-12

TLW #: TLW1530

Date: 8 / 30 / 04Inspector: SWRound Level: 721

- ☒ Measure Headspace Min + .002
- ☒ Sear Engagement: 1st. .0353 2nd. .0351 3rd. .0354 Ave. .0353 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Trigger Pull: 1st. 5.288 2nd. 5.034 3rd. 5.220 Ave. 5.247 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear
- ☒ Inspect stock for any signs of cracking or other failure: Normal 45° Crack at recoil lug - picture taken
- ☒ Other items of note: OK

TLW1216

Remington Confidential

ET22979