

CONFIDENTIAL

Remington Arms Company Inc.
 Research & Development Technical Center
 315 West Ring Road
 Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 / 1 / 04Inspector: SWRound Level: 1221

- ☒ Measure Headspace Min 4.006
- ☒ Sear Engagement: 1st .0333 2nd .0331 3rd .0332 Ave. .0331 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 4.281 2nd 4.295 3rd 4.265 Ave. 4.280 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear, bolt stop little wear
- ☒ Inspect stock for any signs of cracking or other failure. "Normal" 45° Crack through 90% of wall. (Like most others in the test.)
- ☒ Other items of note: OK

TLW1216

Remington Confidential

ET23038