COPIES TO:	C.K. DAVIS D.F. CARPENTER W.O. REISINGER B.E. STRADER F.J. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY BRIDGEPORT	H.K. FAULKNER W.H. DAVIS H.A. BROWN R.H. GRACE H.J. HACKMAN (5) D.S. FOOTE D.E. MILLER S.W. ROSE R.A. WILLIAMSON A.J. BROWN R.E. WRIGHT
TOTAL JUSTIFIED COMPLAINTS	·	
MARCH 1948		218
MARCH 1947		123
TO DATE 1948	•	838
TO DATE 1947		398
FOR 12 MONTHS ENDING MARCH 31	, 1948	2038
FOR 12 MONTHS ENDING MARCH 31	, 1947	1126
	ere.	•
LAST 12 MONTHS RUNNING AVERAG	<b>E</b>	169
LAST 12 MONTHS RUNNING AVERAGE	E ( 1 YEAR AGO )	94
LAST 12 MONTHS RUNNING AVERAGE	E ( 6 MONTHS AGO )	119
		•
COMPLAINTS ON GUNS PRODUCED WITHIN	ONE YEAR	
CURRENT MONTH MARCH 1948		171
OCTOBER 1947		128
MARCH 1947		92
MARCH 1946		0
••••••••••••••••••••••••••••••••••••••		
FOR 12 MONTHS ENDING MARCH 31, 194	3	1621
	•	
LAST 12 MONTHS RUNNING AVERAGE ON (	GUNS	135

SHEET NO 1

## COMPLAINTS ON FIREARMS FOR MONTH ENDED MARCH 31, 1948

	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 81 # JACKET HEAD LOOSE O FAILS TO EJECT O STEMS CHAMBER X NOT ACCURATE X FORE-END SCREW TOO SHORT O JAMS (EXTRACTOR LOOSE) SHARP EDGE ON TANG SCREW IS ABOVE SURFACE	1	24
SPORTSMAN - 12 GA.  D SHELLS STEM CHAMBER  O FAILS TO FEED (CARRIER DOG OUT OF ADJUSTMENT  O TRIGGER BINDS  STOCK BROKEN  O HAMMER OUT OF ADJUSTMENT	T) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1
EXTRACTOR BROKEN  X BARREL FITTED WITH 20 GA. TAKE DOWN SCREW  X CARRIER LATCH FILED TOO MUCH  SPORTSMAN - 16 GA.	1 -6 ;	-8
X CARRIER LATCH OUT OF SHAPE O CARTRIDGE STOP OUT OF ADJUSTMENT EXTRACTOR BROKEN EXTRACTOR FILED TOO MUCH X TEAR IN BARREL	1 1 1	1 1 1 0
SPORTSMAN - 20 GA. STOCK CRACKED	-1-	
MODEL 11 - 12 GA.  O SHELLS STEM CHAMBER  STOCK SPLIT  DEFECTIVE STOCK (POORLY FITTED)  RECEIVER DAMAGED	1 1	2 1 1 2
MAIN SPRING BROKEN BARREL BINDS IN REAR OF RECEIVER  MODEL 11 - 20 GA.	1	1 2
O SHELLS STEM CHAMBER	•	2

SHEFT NO. 2

	•	- <i>•</i>	
	·	PRODUCED WITHIN	
MOD	EL 121	ONE YEAR	TOTAL
X	FTRING PIN STRIKES INSIDE RIM		•
Ö	STEM CHAMBER	2	2
· 0	RETAINER LOOSE	1	1
0	BARREL LOOSE ON RECEIVER	i	i
0	FAILS TO EJECT	i	ż
0	FAILS TO EXTRACT	•	1
X	NOT ACCURATE	2	2
Ó	FAILS TO FEED	1	1
•	CARRIER OUT OF ADJUSTMENT	,	1.
X	FIRING PIN HOLE IN BLOCK OUT OF POSITION	_	1
X	DEFECTIVE BARREL	2	- 5
U	STEMS RETAINER		
			10
MOD	EL 141		
***************************************	FORE-END SPLIT	•	•
0	FAILS TO EJECT	1	;
ŏ	SEAR AND SEAR LOCK OUT OF ADJUSTMENT		• •
ŏ	SEAR AND TRIGGER OUT OF ADJUSTMENT	•	1
ŏ	SHELLS STEM CHAMBER	2	ż
0	FAILS TO FEED	· <b>ī</b>	ī
0	FAILS TO EXTRACT		2
	CARTRIDGE STOP BROKEN	1	. 3
0	FEEDING PLUG GOES BY CARTRIDGE STOP		1
, X	TRIGGER AND RECEIVER VERY LOOSE	1	1
X	MAGAZINE LOOSE (THREADS STRIPPED)	1	Ţ
~	STOCK SPLIT	•	2
X	FRONT SIGHT NOT ALIGNED PROPERLY		!
^	ASSEMBLES HARD RECEIVER CRACKED	•	
X	EXTRACTOR FILED TOO MUCH	" <b>.</b>	i
^	EVINATOR LEEP 100 MONT		-21-
		••	41
MODE	EL 241		
0	FAILS TO DISCONNECT	2	3
×.	POOR NOTCH ON FIRING PIN	ī	ĭ
X	BARREL LOCK DOES NOT QUALIFY	į.	1
•	EXTRACTOR BROKEN		1
0	FAILS TO EJECT	3	. 3
X	SIGHTS OUT OF LINE	S 5	
. X	NOT ACCURATE (MUZZLE UPSET)	2	2
0	CARTRIDGE STOP PLUNGER TOO SHORT OR TOO LONG		j.
v	DEFECT I VE STOCK	. ! 2	1
X	JAMS (POOR CLAW ON EXTRACTOR) STEMS CHAMBER	ج 1	Ş
Ø X	BARREL DAMAGED AT FORE-END SCREW HOLE STUD	i	1
6	ACTION FAILS TO CLOSE PROPERLY	•	1
0	DISCONNECTOR DAMAGED	i	1 .
¥	YOKE GROUND TOO MUCH	i	1
X	FRONT SIGHT SLOT IN BARREL IS OFF	i	1
. 4	promit promit poet in a name to bit	<del>- 2j</del>	

SHEET NO. 3

		•
•	PRODUCED WITHIN	
NORTH OF TO OA	ONE YEAR	TOTAL
MODEL 31 - 12 GA. X RIB ON BARREL POOR SHAPE	2	2
DEFECTIVE BARREL	2	2
X BARREL DENTED AND WRINKLED	2	<b>,</b>
O DROP SHELLS	. ī	ĩ
DEFECTIVE STOCK - GRAIN CHECK	i	1
•		
MODEL 24 46 GA		
MODEL 31 - 16 GA.	•	•
STOCK CHECKED RECEIVER CRACKED		1
FAILS TO FEED	•	
STOCK BROKEN	1.	i.
RIGHT CARTRIDGE STOP NOT ADJUSTED PROPERLY	i	i
	<del>-1-</del>	-5
MODEL 31 - 20 GA.	_	_
O CARTRIDGE STOP OUT OF ADJUSTMENT	1	1
DEFECTIVE STOCK (CHECKED)		_3_
	3	. •
MODEL 37		
DEFECTIVE BOLT	1	1
• • •		-1-
MODEL 510		
X BARREL OUT OF LINE IN RECEIVER		1
O FAILS TO EJECT	•	Ţ
Broken Ejector X Face of Bolt Shallow		1
X BOLT CLOSES HARD	i	i
A SSS GROUP IN S	<del></del>	
MODEL 511		_
N FAILS TO EJECT	1 .	2
O FIRING PIN FOLLOWS DOWN	•	1 .
O SAFE OUT OF ADJUSTMENT # BOLT AND SEAR DAMAGED	•	i.
# BOLT AND SEAR DAMAGED		<del></del>
	•	)
MODEL 512		•
TO CARTRIDGE RETAINER OUT OF ADJUSTMENT	2	3
O EJECTOR TOO LOW	_	1
O FAILS TO EJECT	, ,	, ]
# BOLT PULLS OUT	14	14
BOLT HANDLE LOOSE	. 1	6
X DEFECTIVE BARREL (RIFLING TORN)		2
DAMAGED INSERT CARTRIDGE RETAINER AND SPRING MISSING	į	1
TOP OF INSERT BENT	1	1
INC. AL HIGEN! CFIAL	-22	26
	lin tin	-0

SHEET NO. L

		PRODUCED WITHIN ONE YEAR	TOTAL
MODE	EL 513 STOCK CHECKED FAILS TO EJECT	•	1
X X X	KEYHOLES BOLT PULLS OUT BOLT HANDLE LOOSE	32 1	32
•••	•	36	37
MODE	IL 521 STOCK CHECKED	•	•
0	SAFETY SCREW BROKEN DROP SHELLS	1	1
X	ELEVATION SLIDE COMPLETE MISSING BROKEN MAGAZINE LOCK	į	į
X	BOLT BINDS MOVING FORWARD	1 6	6
MODE	<u>L 550-1</u>		
0	CARTRIDGE STOP BROKEN FAILS TO COCK	2	. 2
X	INSERT ROUGH (JAMS)	<b>ģ</b>	ģ.
OOOOXOXX	FAILS TO EJECT FAILS TO CONNECT	, <b>4</b> ·	4
ŏ	FAILS TO EXTRACT	· ģ	2
0	NO CHAMFER ON FRONT END OF RECOIL CHAMBER	• 1	1
X O	FAULTY TRIGGER PULL LOOSE INSERT	1	1
X	CONNECTOR PIN LOOSE	i	i.
X	TOOL MARKS AROUND RIFLING	1	1
^	TAKE DOWN SCREW BUSHING LOOSE	211	28

CORRECTED IN RECENT PRODUCTION

OVERSIGHT IN INSPECTION
CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY
TEST RESULTING IN MALFUNCTION THROUGH USAGE
NOT COVERED BY INSPECTION

COMPLAINTS RECEIVED DURING MARCH 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL MODEL 81 SPORTSMAN - 12 GA: SPORTSMAN - 16 GA: SPORTSMAN - 20 GA: MODEL 11 - 12 GA: MODEL 11 - 16 GA:	1948	1947 1 6 5 1 4	1946 10 2 1	<u>1945</u>	MISC. & PARTS
MODEL 11 - 20 GA.  MODEL 121  MODEL 141  MODEL 241  MODEL 31 - 12 GA.  MODEL 31 - 20 GA.  MODEL 31 - 20 GA.  MODEL 37	382372	899 194 31 1	2 10 5 1		
MODEL 510 MODEL 511 MODEL 512 MODEL 513 MODEL 521 MODEL 550 MODEL 550-1	2 1	20 20 20 20	3 1 1	•	

H.E.WEEKS:FH 4/2/48.

CHEET NO 6