## **BARBER - PRESALE R 0100414**

COP	IES TO:	C.K. DAV D.E. CAR W.O. REI B.E. STR F.J. CRA G.O. CLI M.R. WAR G.E. PIN A.L. FRE W.L. CLA W.F.H. M BRIDGE	RPENTER SINGER RADER IFFORD RDEN ICKNEY INCH IY WITTLAGE	W.H. H.A: R.H. D.S. D.E. S.W. R.A.	FAULKNER DAVIS BROWN GRACE HACKMAN (6) FOOTE MILLER ROSE WILLIAMSON BROWN WRIGHT	
TOTAL JUSTIFIED COMPLAINTS				•	-	
JUNE 1948					158	
JUNE 1947					117	
TO DATE 1948	÷			1	504	
TO DATE 1947	. •	.5.			770	
FOR 12 MONTHS ENDING JUNE FOR 12 MONTHS ENDING JUNE	•		-		332 259	
LAST 12 MONTHS RUNNING AVI	•				194	
LAST 12 MONTHS RUNNING AVE	: ,			•	104 16 <u>5</u>	
COMPLAINTS ON GUNS PRODUCED W	ITHIN ONE	YEAR		· .		
CURRENT MONTH JUNE 1948		·			132	
JANUARY 1	1948				295	
JUNE 1947					97	
JUNE 1946	٠				<b>O</b> ·	
FOR 12 MONTHS ENDING JUNE 30,	1947			1	858	
LAST 12 MONTHS RUNNING AVERAGE PRODUCED WITHIN ONE YEAR.	E ON GUNS				154	
•						

## ' COMPLAINTS ON FIREARMS FOR MONTH ENDED JUNE 30. 1948.

	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 81 # JACKET HEAD LOOSE O FAILS TO EXTRACT (EXTRACTOR OUT OF ADJUSTMENT) O FAILS TO EJECT O MAIN SPRING BROKEN O FAILS TO FEED O JAMS (EXTRACTOR LOOSE)	1 1 1	6 1 1 1 1
O FORE-END SCREW STUD BECAME LOOSE FORE-ENE POORLY FITTED CARRIER LATCH SPRING TWISTED DEFECTIVE RECEIVER BOLT DOESN'T LOCK OPEN TAKE DOWN SCREW BINDS	i 1 1	i i i
SPORTSMAN - 12 GA. TAKE DOWN SCREW LOOSE DEFECTIVE MAGAZINE	1 1 2	1 1 2
SPORTSMAN - 16 GA.  O FAILS TO FEED  X FAILS TO LOCK OPEN  O FIBRE CUSHION AND RIVET MISSING  X BOLT BINDS	1 -1 -2	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
MODEL 11 - 12 GA.  X POOR BROWNING  STOCK SPLIT  X FORE-END SPLIT	1 1 -3	1 1 3
MODEL 11 - 16 GA. LOOSE BREECH	1	+
MODEL 11 - 20 GA.  X BARREL SHOWS SCRATCHES TRIGGER BINDS	1	1 2
MODEL 121  X FIRING PIN STRIKES INSIDE RIM O BARREL LOOSE ON RECEIVER X NOT ACCURATE FORE-END SPLIT	2	2 2 2
X FACE OF BLOCK ROUGH ACTION DOESN'T LOCK UP X JAMS (SHELLS CATCH BY CTG. STOP) POOR FINISH	1 3 10	1 3 - 13

•	THE VALUE	design.
MODEL 141	_	_
FORE-ENDSPLIT O FAILS TO EJECT	1	· 1
O FAILS TO FEED	. 1	i
CARTRIDGE STOP BROKEN	1	1
O SHELLS FEED HARD UNDER EXTRACTOR X MISFIRES		•
X MAGAZINE LOOSE (THREADS STRIPPED)	1	Ž
X BREECH BLOCK BINDS		-1
	, <b>7</b>	7
MODEL 241	•	
O FAILS TO DISCONNECT X POOR NOTCH ON FIRING PIN	3	<b>3</b> .
X POOR NOTCH ON FIRING PIN O FAILS TO EJECT	單.	耳
X SIGHTS OUT OF LINE	1 .	1
O MISFIRES	Į .	Ţ
X JAMS (POOR CLAW ON EXTRACTOR)	2	3
O STEMS CHAMBER X BARREL BENT	. 2	ž
O FAILS TO COCK	_2_	_2_
	17	10
MODEL 31 - 12 GA.		
FORE-END BROKEN		
	•	•
MODEL 37		•
STOCK BROKEN	2	2. 1
BARREL LOOSE IN BEDDING STOCK SPLIT AT TOE	1	i_
	3	<del>4</del>
MARCI CIA	•	
MODEL 510 O FAILS TO EJECT	1	7
GUN DEFECTIVE	. 1	1
BOLT CLOSES HARD	1	1
# BOLT PULLS OUT SHORT FIRING PIN	i	i
THREADS IN RECEIVER STRIPPED	i	_ <u>i</u> _
	6	. 6
MODEL_511		•
STOCK BROKEN	. 1	1
O EJECTOR OUT OF POSITION		7
N NOT ACCURATE	2	ż
N FAILS TO EJECT O FAILS TO FEED	1	<u>ī</u>
X BARREL NOT STRAIGHT	1	1
O BOLT PULLS OUT		<del> -</del>
	ſ	~

SHEET NO. 3

• *		
	PRODUCED WITHIN	<b>2</b> 0.00.
MODEL 512	ONE YEAR	TOTAL
O CARTRIDGE RETAINER OUT OF ADJUSTMENT	2	3
BOLT HANDLE BROKEN	<u> </u>	<u> </u>
# BOLT PULLS OUT MAGAZINE RING THREADS BAD	<b>7</b>	I
O STEMS CHAMBER	i	1
X BARREL BENT	<u>1</u>	1
JAMS Cartridge Stop Bent	2	2
	76	17
MODEL 513	•	·
X KEY HOLES (POOR RIFLING)	4	4-
BOLT HANDLE BROKEN	1	1
X BOLT HANDLE LOOSE X FRONT SIGHT LOOSE	1	1
A THORE STORE LOSSE	6	<del>-</del>
MODEL 514		
TRIGGER BENT	2	2
SAFE WILL NOT GO ON:	1	
	<b>5</b>	3
MODEL 521		
STOCK CHECKED . O FAILS TO FEED	1	1
X NOT ACCURATE	1	. <b>i</b>
STOCK AND BUTT PLATE BROKEN	•	1
X BOLT HANDLE LOOSE O JAMS		1
		6
MODEL 550-1		• •
O FAILS TO FEED	1	1
X NOT ACCURATE	5	Ę
X JAMS (INSERT ROUGH) O FAILS TO EJECT	Å Å	Ž.
O NO CHAMFER ON FRONT END OF RECOIL CHAMBER	i	ĭ
DEFECTIVE RECOIL CHAMBER	1	1
DEFECTIVE STOCK DISCONNECTOR SPRING WEAK	1 2	1
FAILS TO COCK	1	1
SHELLS EXPLODE OR SWELL:	1	1
DEFECTIVE SIGHT	19	10
	• • •	• 7
MODEL 550 SEAR STUD BROKEN		•
SEAR SIUD BRUNER		and the contract of

_	•	ONE YEAR	TOTAL
MOI	DEL 721	·	
7	STOCK CRACKED AT GRIP	9	9
Ò	FAILS TO EJECT	ź	ź.
X	BOLT CLOSES HARD	· 2	Ž
	NOT ACCURATE	1	ī
X	BAD SPOT IN BARREL	İ	1
0	FAILS TO EXTRACT	i	1
	POOR BEDDING	i i	. 1
		777	77

- # CORRECTED IN RECENT PRODUCTION
- Y OVERSIGHT IN INSPECTION
- O CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY
  TEST RESULTING IN MALFUNCTION THROUGH USAGE,
  N NOT COVERED BY INSPECTION.

COMPLAINTS RECEIVED DURING JUNE 1948 - ON GUNS PRODUCED IN THE FOLLOWING: YEARS.

MODEL	1948	1947	1946	1945	MISC. & PARTS.
MODEL 81 SPORTSMAN - 12 GA.	4 2	4	9		
SPORTSMAN - 12 GA. SPORTSMAN - 16 GA. SPORTSMAN - 20 GA.		2	2		
MODEL 11 - 12 GA. MODEL 11 - 16 GA.	· 3	•			
MODEL 11 - 20 GA.	8	•	1		,
MODEL 121 MODEL 141 MODEL 241	20	3	4		
MODEL 241 MODEL 31 - 12 GA. MODEL 31 - 16 GA.	1	<b>,</b> .	•		
MODEL 31 - 20 GA. MODEL 37	2	<b>9</b> .	•		
MODEL 510 MODEL 511	4	. 2	•		:
MODEL 512 MODEL 513	7	ş	: <b>i</b>	-	
MODEL 514 MODEL 521	ż	1	•		
MODEL 550	14	<b>T</b>	i		•
MODEL 750-1 MODEL 721	14	3			

H.E.WEEKS:FH 7/14/48.

CHEET NO 6