COPIES TO: C.K. DAVIS D.E. CARPENTER W.O. REISINGER B.E. STRADER F.K. CRAIG G.O. CLIFFORD M.R. WARDEN G.E. PINCKNEY A.L. FRENCH W.L. CLAY W.F.H. MATTLAGE BRIDGEPORT	H.H. FAULKNER W.H. DAVIS H.A. BROWN R.H. GRACE H.J. HACKMAN (6) D.S. FOOTE D.E. MILLER S.V. ROSE R.A. WILLIAMSON A.J. BROWN R.E. WRIGHT
TOTAL JUSTIFIED COMPLAINTS	
JULY 1948	272
JULY 1947	139
TO DATE 1948	1776
TO DATE	909
FOR 12 MONTHS ENDING JULY 31, 1948	2365
FOR 12 MONTHS ENDING JULY 31, 1947	1324
LAST 12 MONTHS RUNNING AVERAGE	197
LAST 12 MONTHS RUNNING AVERAGE (1 YEAR AGO)	110
LAST 12 MONTHS RUNNING AVERAGE (6 MONTHS AGO)	161
COMPLAINTS ON GUNS PRODUCED WITHIN ONE YEAR	
CURRENT MONTH JULY 1948	240
FEBRUARY 1948	172
JULY 1947	115
JULY 1946	Q
FOR 12 MONTHS ENDING JULY 31, 1948	1983
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE WEAR.	165

COMPLAINTS ON FIREARMS FOR MONTH ENDED JULY 31. 1948

	PRODUCED WITHIN	TOTAL
MODEL 81 # JACKET HEAD LOOSE O FAILS TO EJECT O MAGAZINE FOLLOWER BINDS REAR SIGHT LOOSE	2 2 5	4 2 2 1 9
SPORTSMAN - 12 GA. THREADS ON TAKE DOWN SCREW STRIPPED X RECEIVER CUSHION LOOSE O TAKE DOWN SCREW DAMAGED	2 1 1 4	2 1 1
SPORTSMAN - 16 GA. O RECEIVER CRACKED AT FRONT END FIRING PIN RETAINING PIN BROKE	1 2	1 2
SPORTSMAN - 20 GA. O FAILS TO EJECT		1.
MODEL 11 - 12 GA. BREECH BLOCK CRACKED NICKS IN BARREL AT MUZZLE	-1-	2 1 3
MODEL 11 - 16 GA. STOCK CHECKED		1
MODEL 11 - 20 GA. BARREL STICKS BACK , BOLT BINDS		

CHEET NO 2

	·	PRODUCED WITHIN	TOTAL
MOD X O	EL 121 FIRING PIN STRIKES INSIDE RIM STEMS CHAMBER	2	3
0 0 X	FAILS TO EJECT FAILS TO EXTRACT NOT ACCURATE	1	1
O X	FAILS TO FEED ACTION BAR MACHINED WRONG	2 1 1	2 1 2
X O	MISFIRES FORE-END SPLIT STEMS RETAINER	1 2	2
X	JAMS (SHELLS CATCH BY CARTRIDGE STOP) RECEIVER AND GUARD LOOSE	18	1 22
MODI	EL 141 SEAR AND SEAR LOCK OUT OF ADJUSTMENT CARTRIDGE STOP BROKEN	ļ. 1	3
, X	NOT ACCURATE ACTION BINDS ACTION BAR LOCK WORN		1
MODE	EL 241	7	10
0	CARTRIDGE STICKS IN CARTRIDGE GUIDE FEEDING	•	•
O X	FAILS TO DISCONNECT POOR NOTCH ON FIRING PIN EXTRACTOR BROKEN	3	8
O X	FAILS TO EJECT SIGHTS OUT OF LINE	h 1	6
ô	TAKE DOWN LOOSE STOCK BROKEN	1	
O X	FAULTY TRIGGER PULL DISCONNECTOR SHORT	1	j
X	JAMS (POOR CLAW ON EXTRACTOR) FAILS TO OPERATE PROPERLY	. 4 1	4 1
O X X	DISCONNECTOR DAMAGED CARTRIDGE GUIDE OUT OF POSITION BARREL BENT	1 1 h	1
ô	FAILS TO COCK INNER MAGAZINE TUBE LOOSE	2	2
	SCRATCH ON LANDS OF BARREL 6" FROM MUZZLE BARREL ADJUSTING HOLE IN RECEIVER MACHINED WRONK	ž Į	2 1
	SAFETY OPERATES HARD EXTRACTOR SPRING AND PLUNGER DAMAGED	39	44
MODE	L 31 - 12 GA.	,	•
0	CARTRIDGE STOP OUT OF ADJUSTMENT FORE-END BROKEN	1	1
0	EROP SHELLS ACTION BAR BROKEN	i	1
	MAGAZITE FOLLOWER BINDS FIRING PIN BINDS	1	1
X	MAGAZITE TUBE LOOSE IN RECEIVER	-1 -5	+

•	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 31 - 16 GA.		
STOCK CHECKED	1	1
DEFECTIVE CARRIER	-1-	
	-	_
MODEL 31 - 20 GA. O CARTRIDGE STOP OUT OF ADJUSTMENT		1
DEFECTIVE STOCK	2	2
RIGHT CARRIER STUD COMES OUT OF REC		1
	2	4
MODEL 37		
STOCK BROKEN	2	2
X TRIGGER PULL NOT PROPERLY ADJUSTED X NOT ACCURATE	1	2
V (M) Noodinia	3	5
MODEL ELO		_
MODEL 510 BOLT HANDLE BROKEN	·.	1
INACCURATE	2	Ż
SAFETY LOOSE (SLEEVE PIN SHORT)		1
	3	• •
MODEL 511	3	
N FAILS TO EJECT FAILS TO FEED	.	Ž
SEAR DAMAGED	ī.	Ī.
DEFECTIVE BOLT HOLE	1	1
RECEIVER CHIPPED AT BREECH X NO HOLES DRILLED AND TAPPED FOR SIG	HTS 1	i
JARS OFF		
	10	10
MODEL 512	• .	
O CARTRIDGE RETAINER OUT OF ADJUSTMENT	r ·	10
O FAILS TO FEED N BARREL LOCK PIN HOLES LARGE	. 2	1
O FAILS TO EJECT	, ć	Ż
N NOT ACCURATE	1 2	1
SEAR BROKEN X BARREL BENT	3) I
X BARREL BENT X FAILS TO FUNCTION PROPERLY # BOLT PULLS OUT	_1	1
# BOLT PULLS OUT BOLT HANDLE LOOSE	13	13
CARTRIDGE STOP BENT	i	ī
O FAILS TO EXTRACT	1.	1
CAM ROUGH DEFECTIVE OUTER MAGAZINE (BENT)	1	1
DELEGIIAE AGIPU LAGRETISE (mail)	42	45

SHEET NO. L

.•		PRODUCED WITHIN	70741
•		ONE YEAR	TOTAL
MOD	EL 513		
0	FAILS TO EJECT		1
X	KEY HOLES (POOR RIFLEING) BOLT PULLS OUT	7	8
X	BOLT PULLS OUT		
	. •	8	10
MOD	EL 514		
-144	TRIGGER BENT	3	3
	SAFETY OUT OF ADJUSTMENT	7	7
	DEFECTIVE BOLT	<u> </u>	<u>i</u>
		8	8
		•	•
X	EL 521 NOT ACCURATE		•
^	REAR SIGHT MISSING (BASE SCREW BENT)	. 1	1
X	BOLT HANDLE LOOSE	Ş	ş
••	STOCK CRACKED	1	
•	STOCK MARRED	i	i
0	JAMS :	1	_i_
		8	8
MODE	7L_550-1		
0	FAILS TO FEED	5	5
·X	NOT ACCURATE	Ź	Ź
0	FAILS TO COCK	4	. 4
X	JAMS (INSERT ROUGH)	7	7
X 0 0	SEAR SPRING CASE NOT SCREWED UP TIGHT FAILS TO EJECT	16	1
X	FAIS TO CONNECT	12	ני
•	BROKEN EXTRACTOR	1	1
X.	RECOIL CHAMBER SHALLOW	i	i
	MISFIRES	Ì	1
	DEFECTIVE RECOIL CHAMBER (RINGS)	2	2
X	TOOL MARKS AROUND RIFLEING	1	1
X	TAKE DOWN SCREW BUSHING LOOSE CONNECTOR SPRING WEAK	. 2	2
	ACTION SPRING DAMAGED	i	1
	STOCK SPLIT AT TIP	i	•
•	THREADS IN MAGAZICE RING HOLE IN BARREL POOR	i	i
	SHELLS SWELL	i	i
	REAR SIGHT NOT ALIGNED PROPERLY	1	1
	FIRING PIN DAMAGED	1	1
	BOLT PULLS OUT	- <u>-</u> !	<u>_</u>
		21	זכ

SHEET NO. 5

	PRODUCED WITHIN	TOTAL
MODEL 721		
# STOCK CRACKED AT GRIP	8	8
SAFETY BROKEN	1	ī
X BOLT CLOSES HARD	1	1
DEFECTIVE BOLT	7	1
X NOT ACCURATE	1	1
X SIGHTS NOT PROPERLY ALIGNED	1	1
COCKING CAM IN BOLT UPSET	1	1
X DEFECTIVE CHAMBER	1	1 .
FORE-END CRACKED	1	1
SWELL IN BARREL AT REAR OF FRONT SIGHT RAMP	<u>l</u>	
·	17	17
MODEL 722		
STOCK SPLIT	4	4
·	ĨŢ.	14

CORRECTED IN RECENT PRODUCTION.

OVERSIGHT IN INSPECTION.

CLOSE ADJUSTMENT NOT SHOWING UP IN FACTORY TEST
RESULTING IN MALFUNCTION THROUGH USAGE.

NOT COVERED BY INSPECTION.

COMPLAINTS RECEIVED DURING JULY 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL	1948	1947	1946	1945	MISC. & PARTS
MODEL 81 SPORTSMAN - 12 GA. SPORTSMAN - 16 GA. SPORTSMAN - 20 GA. MODEL 11 - 12 GA. MODEL 11 - 16 GA. MODEL 11 - 20 GA. MODEL 121 MODEL 121 MODEL 141 MODEL 241 MODEL 31 - 12 GA. MODEL 31 - 16 GA. MODEL 31 - 20 GA. MODEL 510 MODEL 511 MODEL 512 MODEL 513 MODEL 514 MODEL 521	1948 14 1 1 1857212 2251824	1947 1 1 10 10 12 13 1 7	1946 4 1 2 1 4 7 5 2 2 2 1 3 2	1945	MISC. & PARTS
MODEL 550-1 MODEL 721 MODEL 722	39 16 4	12			·

h.e.**weeks:F**h 8/10/48