F. K G.O M.R G.E A.L W.L W.F	CARPENTER W.H. DAVIS
TOTAL JUSTIFIED COMPLAINTS	
AUGUST 1948	<b>96</b>
AUGUST 1947	81
TO DATE 1948	1872
TO DATE 1947	990
	• •
FOR 12 MONTHS ENDING AUGUST 31, 1948	2380
FOR 12 MONTHS ENDING AUGUST 31, 1947	1366 ·
LAST 12 MONTHS RUNNING AVERAGE	198
LAST 12 MONTHS RUNNING AVERAGE ( 1 YEAR	AGO ) 113
LAST 12 MONTHS RUNNING AVERAGE ( 6 MONTH	is AGO ) 169
COMPLAINTS ON GUNS PRODUCED WITHIN ONE YEAR	• •
CURRENT MONTH AUGUST 1948	86
MARCH 1948	171
AUGUST 1947	66
AUGUST 1946	o
•	.:
FOR 12 MONTHS ENDING AUGUST 31, 1948	2003
LAST 12 MONTHS RUNNING AVERAGE ON GUNS PRODUCED WITHIN ONE YEAR.	166

## COMPLAINTS ON FIREARMS FOR MONTH ENDED AUGUST 31, 1948.

:	PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 81 # JACKET HEAD LOOSE O FAILS TO EJECT O MAGAZINE SIDE SPRING OUT OF ADJUSTMENT X NOT ACCURATE TAKE DOWN SCREW BINDS	1 2 1 1 6	2 1 2 1 1
SPORTSMAN - 12 GA.  MAIN SPRING BROKEN  O TRIGGER BINDS  FORE-END SPLIT  O FAILS TO EJECT	1	1 1 1 1
SPORTSMAN - 16 GA. O TRIGGER BINDS		
MODEL 11 - 12 GA.  O SHELLS STEM CHAMBER O FAILS TO EJECT	1	· 2 1 3
MODEL 11 - 20 GA.  O SHELLS STEM CHAMBER  X FRONT SIGHT BASE OUT OF POSITION	-1-	1 2
MODEL 121 FIRTNG PIN BROKEN O SHELLS STEM CHAMBER O TAKES MAX. PLUG O FAILS TO EJECT O FAILS TO FEED	1	1 2 1 1 1
MODEL 141 O SHELLS STEM CHAMBER CARTRIDGE STOP BROKEN X FIRING PIN HOLE OUT OF POSITION	2 2	2 2

MODEL 241	PRODUCED WITHIN ONE YEAR	TOTAL
O FAILS TO DISCONNECT X POOR NOTCH ON FIRING PIN O FAILS TO EJECT X SIGHTS OUT OF LINE X NOT ACCURATE (MUZZLE UPSET) O CARTRIDGE STOP OUT OF ADJUSTMENT X POOR BLUEING X JAMS ( POOR CLAW ON EXTRACTOR ) O SHELLS STEM CHAMBER DEFECTIVE BARREL O DISCONNECTOR DAMAGED O FAILS TO COCK RECEIVER CRACKED	1 2 2 1 1 1 1 1 2 1	122111111111111111111111111111111111111
MODEL 31 -12 GA. DEFECTIVE BARREL		1
MODEL 510 U FATES TO EXTRACT TAKE DOWN SCREW THREADS BAD IN RECEIVER	1 1 2	1 1 2
MODEL 512 U CARTRIDGE RETAINER OUT OF ADJUSTMENT O FAILS TO EJECT # BOLT PULLS OUT N NOT ACCURATE (SIGHTS OUT OF LINE)	3	1 1 3
MODEL 513 X KEY HOLES ( POOR RIFLEING)	6	_6_
MODEL 514 X DEFECTIVE BOLT BOLT HANDLE BROKEN	1 2	1 1 2-
MODEL 521 X BOLT HANDLE LOOSE	1	1

		PRODUCED WITHIN ONE YEAR	TOTAL
MODEL 550-1  X NOT ACCURATE  X JAMS (INSERT ROUGH)  O FAILS TO EJECT  O FAILS TO CONNECT  BROKEN EXTRACTOR  FAILS TO OPERATE PROPER  SHELLS STEM CHAMBER  CONNECTOR SPRING WEAK  X BOLT BINDS  SHELLS SWELL	LY	122112211	1221112211
DEFECTIVE BOLT POOR THREADS IN RECEIVE	R	1 10	16
MODEL 721 # STOCK CRACKED AT GRIP O FAILS TO EJECT		Z	7
DEFECTIVE BOLT  X BAD SPOT IN BARREL  • EXTRACTOR LOOSE  SEAR BINDS		1	1 1
O TRIGGER PIN OUT OF POSI	TION .	15	15
MODEL 722 BOLT HANDLE CRACKED BOLT CRACKED		1	1
X BARREL LOOSE IN RECEIVED	?	- 1	<u>i</u>

CORRECTED IN RECENT PRODUCTION
OVERSIGHT IN INSPECTION
CLOSE ADJUSTMENT NOT SHOWING UP IN
FACTORY TEST RESULTING IN MALFUNCTION
THROUGH USABE

NOT COVERED BY INSPECTION

COMPLAINTS RECEIVED DURING AUGUST 1948 - ON GUNS PRODUCED IN THE FOLLOWING YEARS.

MODEL	1948	1947	1946	1945	MISC. & PARTS
MODEL 81 SPORTSMAN - 12 GA. SPORTSMAN - 16 GA.	1	5	1		
SPORTSMAN - 20 GA. MODEL 11 - 12 GA. MODEL 11 - 16 GA.	1.		2		· .
MODEL 11 - 20 GA. MODEL 121 MODEL 141	1 1 3	1 2 6	1 .		
MODEL 241 MODEL 31 - 12 GA. MODEL 31 - 16 GA.	18	6	1		
MODEL 31 - 20 GA. MODEL 37 MODEL 510		2			
MODEL 511 MODEL 512 MODEL 513	1 	5			٠.
MODEL 514 MODEL 521 MODEL 550-1	16	•			
MODEL 721 MODEL 722	3		* * .	•.	

H.E.WEEKS:FH 9/8/48