

Microsoft Excel - DAT - Overall Summary

File Edit View Insert Format Tools Data Window Help

AA19

	T	U	V	W	X	Y	Z	AA	AB	AC	AD	AE
	Drop at	Drop at	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	50 Lb. Trigger Pull Test	Magazine	
	Heel	Toe	Trigger Pull	Trigger Pull	Engagement	Engagement	Trigger Gap	Trigger Gap	Fire During	Fire After	Capacity	
	(in.)	(in.)	Before (lbs.)	After (lbs.)	Before (in.)	After (in.)	Before (in.)	After (in.)	Safe Release	Trigger Pull	Test	
1	1.417	6.278	5.00	5.08	0.0276	0.0293	0.162	0.140	NO	YES	OK	
2	1.406	6.295	5.08	5.25	0.0282	0.0287	0.163	0.132	NO	YES	OK	
3	1.398	6.305	4.58	4.92	0.0251	0.0263	0.166	0.124	NO	YES	OK	
4	1.401	6.306	4.92	4.75	0.0280	0.0279	0.165	0.123	NO	YES	OK	
5	1.404	6.279										
6	1.392	6.289	4.92	4.75	0.0280	0.0301	0.166	0.136	NO	YES	OK	
7	1.391	6.297	4.42	4.75	0.0282	0.0307	0.167	0.136	NO	YES	OK	
8	1.391	6.292	5.33	5.00	0.0299	0.0282	0.168	0.149	NO	YES	OK	
9	1.415	6.310	4.83	4.50	0.0304	0.0290	0.164	0.128	NO	YES	OK	
10	1.407	6.308	5.17	5.17	0.0265	0.0281	0.165	0.128	NO	YES	OK	
11	1.402	6.296	4.92	4.91	0.0280	0.0287	0.165	0.133				
12	1.417	6.310	5.33	5.25	0.0304	0.0307	0.168	0.149				
13	1.391	6.278	4.42	4.50	0.0251	0.0263	0.161	0.123				
14	0.009	0.012	0.28	0.24	0.0016	0.0013	0.062	0.008				
15												
16												
17												
18												
19												
20												
21												
22												
23												
24												
25												
26												
27												
28												
29												
30												
31												

Detailed Measurements-Gun / Detailed Measurements-Bill / Jack Function / Shoulder Function / Endurance / Abuse Tests

Draw AutoShapes

Ready

Start Inbox - Microsoft Exchange Microsoft Excel - DA Exploring J:\Phase 2

NUM 8:24 AM