

RE FUNCTION TEST

From: Reesor, Phillip K.
Sent: Tuesday, September 12, 2000 1:05 PM
To: Danner, Dale; Franz, Scott
Subject: RE: FUNCTION TEST

Latest is that the mag box in two rifles has come apart one time.

From: Reesor, Phillip K.
Sent: Tuesday, September 12, 2000 11:51 AM
To: Danner, Dale; Franz, Scott
Subject: FUNCTION TEST

First reports from function testing are that the feeding seems ok, however the bolt operation is very stiff, especially the downward movement of the bolt to lockup the action. Not smooth at all. 83

PKR

CONFIDENTIAL