endurance1000rd

From: Reesor, Phillip K.

Sent: Sunday, September 17, 2000 9:20 AM

To: Franz, Scott

Cc: Arnold, Jesse T.; Lee, Robert

Subject: endurance

Scott, during the 1000 rd. level clean & inspect the bolt handle broke off of gun B-14,

I instructed Bob & Jesse to replace it with B-17 for the extended end

urance test. B-17

to B-20 were not scheduled to be tested any further than 1000 rds. or involved in any

other additional testing.



Page 1