

M-600
CAL 222
Pilot Line

1-15-64

Gun erial No.	Headspace		Ammu- tion	Rounds	No. Malf	Type of Malfunction	Trigger Pull (lbs.)			Accuracy (inches) Center to Center							
	Go	No Go					Avg. of 10			Accuracy Device				Shoulder			
							Max.	Min.		5-Shot Group				5-Shot Group			
										1	2	3	Avg.	1	2	3	Avg.
2815	OK	OK	Win. PSP	20	4	2 Stem Right	3.5	4.0	3.25	2.0	1.45	1.85	1.73	1.55	2.6	2.0	2.0
			Rem. SP	20	0	2 Stem low											
2757	OK	OK	Win. PSP	20	0												
			Rem. SP	20	0		6.98	9.25	5.0	3.2	2.5	2.0	2.56	1.5	2.15	1.95	1.86
2880	OK	OK	Win. PSP	20	0		See Footnote 1										
			Rem. SP	20	0					3.05	2.0	1.9	2.31	1.8	1.55	1.4	1.58
3187	OK	OK	Win. PSP	20	0		5.43	5.75	5.0	2.72	2.2	2.85	2.59	2.0	1.4	2.15	1.85
			Rem. SP	20	0												
2825	OK	OK	Win. PSP	20	3	1 Stem low 2 Stem hi - left	7.65	9.5	5.0	4.1	1.9	2.55	2.85	3.0	1.6	1.6	2.06
			Rem. SP	20	0												
759	Tight	OK	Win. PSP	20	0		4.0	4.5	3.75	3.6	4.1	1.8	3.16	3.1	2.8	1.85	2.58
			Rem. SP	20	0												
863	OK	OK	Win. PSP	20	2	1 Stem hi - left 1 Stem right	3.25	4.5	2.75	1.75	1.6	2.5	1.95	1.85	1.35	2.5	1.9
			Rem. SP	20	0												
845	OK	OK	Win. PSP	20	3	2 Stem hi - left 1 Stem hi - right	4.83	5.5	4.25	2.3	1.5	2.2	2.0	1.65	1.3	.5	1.15
			Rem. SP	20	2	2 Stem right											
769	OK	OK	Win. PSP	20	1	Tight under rail	5.53	6.25	4.75	4.7	2.42	2.65	3.25	.74	.75	2.3	1.26
			Rem. SP	20	0												
2821	OK	OK	Win. PSP	20	0		5.85	6.5	5.25	2.3	1.3	1.4	1.66	1.6	1.3	1.92	1.9 1.6
			Rem. SP	20	0												

1. Bolt Jammed. When disassembled, small Piece of Nylon Found To cause Jam.

BARBER - PRESALE R 0102568

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON

BARBER - PRESALE R 0102568
R2503556