

17-000
C112-012
Pilot Line

Gun Serial No.	Headspace		Ammuni- tion	Rounds	No. Malf.	Type of Malfunction	Trigger Pull (lbs.)			Accuracy (Inches) Center to Center							
										Accuracy Device				Shoulder			
	Go	No Go					Avg. of 10	Max.	Min.	5-Shot Group				5-Shot Group			
										1	2	3	Avg.	1	2	3	Avg.
815	OK	OK	Win. PSP Rem. SP	20 20	4 0	2 Stem Right 2 Stem low	3.5	4.0	3.25	2.0	1.45	1.85	1.73	1.55	2.6	2.0	2.01
2757	OK	OK	Win. PSP Rem. SP	20 20	0 0		6.98	9.25	5.0	3.2	2.5	2.0	2.56	1.5	2.15	1.95	1.86
2880	OK	OK	Win. PSP Rem. SP	20 20	0 0		See Footnote 1			3.05	2.0	1.9	2.31	1.8	1.55	1.4	1.58
3187	OK	OK	Win. PSP Rem. SP	20 20	0 0		5.43	5.75	5.0	2.72	2.2	2.85	2.59	2.0	1.4	2.15	1.85
2825	OK	OK	Win. PSP Rem. SP	20 20	3 0	1 Stem low 2 Stem hi - left	7.65	9.5	5.0	4.1	1.9	2.55	2.85	3.0	1.6	1.6	2.06
2759	Tight	OK	Win. PSP Rem. SP	20 20	0 0		4.0	4.5	3.75	3.6	4.1	1.8	3.16	3.1	2.8	1.85	2.58
2863	OK	OK	Win. PSP Rem. SP	20 20	2 0	1 Stem hi - left 1 Stem right	3.25	4.5	2.75	1.75	1.6	2.5	1.95	1.85	1.35	2.5	1.9
2845	OK	OK	Win. PSP Rem. SP	20 20	3 2	2 Stem hi - left 1 Stem hi - right 2 Stem right	4.83	5.5	4.25	2.3	1.5	2.2	2.0	1.65	1.3	.5	1.15
2769	OK	OK	Win. PSP Rem. SP	20 20	1 0	Tight under rail	5.53	6.25	4.75	4.7	2.42	2.65	3.25	.74	.75	2.3	1.26
2821	OK	OK	Win. PSP Rem. SP	20 20	0 0		5.85	6.5	5.25	2.3	1.3	1.4	1.66	1.6	1.3	1.92	1.6

1. BOLT JAMMED. When disassembled, small piece of Nylon found to cause Jam.

BARBER - PRESALE R 0102570

CONFIDENTIAL-SUBJECT TO PROTECTIVE ORDER
KINZER V. REMINGTON

BARBER - PRESALE R 0102570 R2503558