cc: S. M. Alvis

210 HOXE

October 5, 1965

H. J. HACKMAN

Trigger Housing Assembly • M/700 and M/40XB

Would you please give us a cost estimate on assembly of the Model 700 and M/40XB Trigger Housing with 3/32" headed rivets as per the attached drawings.

The sear and trigger pin holes can be brought up to finished size before assembly if it is felt that sufficient alignment of these holes can be maintained during riveting. If alignment can be maintained, then the hole for the safety detent ball should be hardened prior to assembly.

A. M. Freund Lion Research Division

AMF:nl