

REMINGTON ARMS COMPANY, INC.

ENGINEERING DEPARTMENT

COMPUTATION SHEET

TITLE OF PRG.

Paddy Metal Tear test

PAGE NO

SUBJECT

H700 ~~metal~~ - ZERO CYCLES

WORKS

Testing can surface lubricated with grease) COMPUTER D.U.R.T.R

DATE June 28

1965

old Crushers

at 0 cycles.

X

#139413 PM

#139555 PM

#139457 PM chmn

trigger pull F.P. indent

trigger pull F.P. indent

trigger pull F.P. indent

5.50 .0175

5.50 .0185

5.50 .018

5.75 .017

6.00 .0185

5.25 .018

6.00 .0185

5.50 .019

5.00 .0185

6.25 .018

6.00 .0185

5.00 .018

6.50 .018

5.25 .0185

4.75 .0185

6.00 .0178

5.65 .0186

5.10 .0182

#139312 PM chmn

#153959 Std. Prod

#154225 Std. Prod.

trigger pull F.P. indent

trigger pull F.P. indent

trigger pull F.P. indent

4.75 .0175

6.50 .0195

5.25 .0175

4.50 .0175

6.00 .014

5.75 .0175

4.50 .017

6.25 .015

5.50 .0175

4.50 .017

6.75 .014

5.25 .019

4.75 .0175

5.50 .015

5.25 .0185

4.60 .0173

6.30 .0145

5.40 .018

#139298 mach. ser.

#139609 mach. ser.

trigger pull F.P. indent

trigger pull F.P. indent

3.50 .018

5.25 .018

3.50 .018

5.25 .0165

3.75 .0185

5.50 .0175

3.50 .019

5.50 .0175

3.75 .019

5.50 .0165

3.60 .0185

5.40 .0172

* Run #139200 & 139609 after cannot work. John Brooke knows and wants to test on new.

1/5 new crusher.

old crusher.

Rem. new crusher from Winchester. Took order

5.50 .018

5.75 .019

with new crusher and again with the old one

5.75 .018

5.25 .0175

using gun #139555

5.75 .018

6.25 .0185

5.50 .018

6.00 .018

6.00 .0175

5.75 .0175

REMINGTON ARMS COMPANY

ENGINEERING DEPARTMENT

COMPUTATION SHEET

PROJECT :

SUBJECT :

COMPUTER

NO 66-8