

11-11-6

after 11-10-65 tests

Rifle 139413

5 ear can surface that contacts F. Fin. head surface.

Shiny spots showing some wear but not excessive.

5 ear surface that contacts connector surface
Some varnish or rust showing, a black substance like grease piled up where connector contacts a stop.

^{black substance} varnish or rust.

connector surface shows some varnish or rust

Rifle 139555

5 ear can surface - same as above

5 ear surface that contacts connector a large amount varnish or rust covering most of contact surface

Connector surface shows most of contact area covered with varnish or rust,

* 5 ear can surface were touched during inspection but other surfaces were not. Fire controls remain to riders.