


300 WM Strains 710 Brl. A-14

Tlr 896 Shot:	Scope Volts		Gage 2 Ohm Meter Volts			Notes:	1-Jul-02 Scope:
	Gage 1	Gage 2	Before	After	Diff:		
Calib:	.990	1	.000	.000		Calib.	500mv / 500us / 100mv Chl 2
1	Clip	.600	.000	.003	.003	150g	500mv / 500us / 100mv Chl 2
2	.650	1.14	.000	.193	.193	Proof	500mv / 500us / 100mv Chl 2
3	No Trigger		.193	.408	.215	Proof	500mv / 500us / 100mv Chl 1
4	.710	1.50	.408	.619	.211	Proof	500mv / 500us / 100mv Chl 1
5	.770	1.78	.617	.869	.252	Proof	500mv / 500us / 100mv Chl 1
6	Clip	Clip	.866	1.048	.182	Proof	500mv / 500us / 100mv Chl 1
7	.790	2.04	1.046	1.187	.141	Proof	500mv / 500us / 100mv Chl 1
8	.890	2.20	1.180	1.294	.114	Proof	500mv / 500us / 100mv Chl 1
9	.990	2.36	1.290	1.446	.156	Proof	500mv / 500us / 100mv Chl 1
10	.970	2.52	1.444	1.59	.146	Proof	500mv / 500us / 100mv Chl 1
11	1.110	2.70	1.587	1.762	.175	Proof	500mv / 500us / 100mv Chl 1
12	No Trigger		1.760	1.860	.100	Proof	500mv / 500us / 100mv Chl 1
13	1.090	2.86	1.848	1.917	.069	Proof	500mv / 500us / 100mv Chl 1
14	1.190	2.92	1.910	1.989	.079	Proof	500mv / 500us / 100mv Chl 1
15	1.230	2.96	1.988	2.050	.062	Proof	500mv / 500us / 100mv Chl 1
16	1.150	3.20	2.054	2.211	.157	Proof	500mv / 500us / 100mv Chl 1
17	1.090	3.20	2.201	2.242	.041	Proof	500mv / 500us / 100mv Chl 1
Max:	1.23	3.20	Sum:		2.296		



	Gage 1	Gage 2
Before	121.2	120.8
After	121.4	121.4
Diff.	+ 0.2	+ 0.6
Ohms		

ET28171