

DATES AND REASONS FOR REVISIONS 10-9-72 - Revised - NWM/RLJ/hv
 4/1/76 - Reviewed for feasibility - NWM/GRB/Jc
 9/30/80-Updated model listing for Malf. #102-JJB/MAB/bdm

DESCRIPTIVE INFORMATION

Proof Malfunctions: Explanation & Coding to be used in reporting Proof Test Results

<u>No.</u>	<u>Abr.</u>	<u>Malfunction</u>	<u>Model Involved</u>	<u>Explanation</u>
180	AI-P	Assembly Incomplete - Proof	All	Working parts of gun omitted - Inoperable.
181	BC-P	Blows Cases-Proof	All	Brass is torn or split open anywhere. (Not blown primer)
182	BEB-P	Barrel Extension broken - Proof	All S.G., 742, 760, 7400, 7600	S.E.
183	BS-P	Barrel split-Proof	All	S.E.
184	DLOS-P	Doesn't lock over shell - Proof	All	Bolt will not close & lock over chambered round.
185	ESB-P	Ejector sticks back - Proof	All C.F. Rifles	After Proof round is fired, Action is operated and Ejector fails to return to its full forward position.
186	PF-P	Fails to fire-Proof	All	S.E.
187	GRSO-P	Guide Ring shot off - Proof	48, 870	Guide Ring separated completely from Barrel, or loose.
188	GCSO-P	Gas Cylinder shot off - Proof	1100	Gas Cyl. separated completely from Barrel, or loose.

PART NAME Proof Malfunctions COOLANT _____ SET UP _____ MODEL No. _____ OPER. No. _____
 TYPE Explanation & Code Nos. -Proof Test Results MACH. HRS. _____ DEPT. No. _____ PAGE 1 OF 2
 MACHINE _____

RECEIVED BY 444

DATES AND REASONS FOR REVISIONS 10-9-72 - Revised - NWM/RLI/hv
 3-22-74 - Item 194 - PP-P - NWM/TIL/hv -- 12-13-74 - Added Items 191, 192, 193, 195 - NWM/GRB/hv
 4/1/76 - Reviewed for feasibility - NWM/GRB/jc
 9/30/80-Updated model listing for Malf., #189, 190, 192, 193-JJB/MBA/bdm

DESCRIPTIVE INFORMATION

No.	Abr.	Malfunction	Model Involved	Explanation
189	BLSO-P	Barrel Lug shot off - Proof	742, 7400	Bbl. Lug separated completely from Barrel, or loose..
190	BRB-P	Breech Ring broken - Proof	742, 760, 7400 7600	S.E.
191	MCSO-P	Magazine Cap shot off - Proof	1100	Magazine Cap shoots off Mag. tube due to insufficient thread engagement.
192	DLO-P	Doesn't lock open - Proof	48, 742, 1100, 7400	Bolt fails to remain in rearward position after proof round was fired.
193	FESO-P	Fore-End shot off - Proof	742, 1100, 7400	S.E.
194	PP-P	Pierced Primer-Proof	All	S.E.
195	BP-P	Blown Primer - Proof	All	Primer is blown out or is loose in primer pocket.
200		Uncoded Proof Malfunctions	All	Any Proof Malfunction not currently listed above.

PART NAME Proof Malfunctions COOLANT _____ SET UP TIME _____ MODEL No. _____ OPER. No. _____
 TYPE Explanation & Code Nos.-Proof Test Results MACH. HRS. _____ DEPT. No. _____ PAGE 2 OF 2
 MACHINE _____