

Barnet, V.P. of R.I.D., then over V.P. of
for the same V.P. of R.I.D.

Notes on Barnes Records

M/700 Final assembly + Final inspection

① Records for previous to 3/71 - includes step 17
on adjustment of overhaul to insure the work

② Records for 3/73 - 11/80 - no step 17 on
overhaul adjustment 3/27/75 record
has step 18 - Final test

Has then test in 3/73 double change from
.0074 .005 clearance

Nothing in pre/75 records about a test of
safety = to safety performance check

11/80 records have .006 shown

M/700 Tagger Assembly.

Records 1972 to 8/79 suggest comparison used
to set standard to zero

8/79 - 8/80 - Previous records have
W.A.W. initials in them -

Records refer to .006 stem for connector

Repeats to Felling Fixture for falling of trigger

11/80 funds has RLG (R + 2m units)

Proof, Test, Target-

Calley Test - Process records 10/75-4/79 -
 suggest that in this time period of tests
 safety performance type test + bench test were both
 performed on rifles in gallery -

* But tests 1967-10/75 - Not indicate
 even safety performance type test was performed
 (this not consistent of testimony in my
 interview of testimony)

Group initials on documents for 11/80 by great
 Proof, test + target records

Microfilm Records on LERs

*Similar in some as Arms Sales Review depression
where ET hanson, JE Presser
Published in letters to customers*