

Technical Services Staff Meeting - March 25

Page 3

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE



"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

Ilion, New York
March 19, 1974

TO: D. S. HARDY

FROM: B. C. PROSSER

SUBJECT: UNIAPT AND POST-PROCESSOR STATUS

UDS

At present there is only one problem with UDS. When a program is being executed thru the post-processor, a page of paper is skipped for every page that is printed. United computing is aware of the problem and is working on a solution. A correction for this should be received by approximately April 15, 1974.

MILWAUKEE-MATIC POST-PROCESSOR

At this time, it cannot be determined if a problem exists with X-Z and Y-Z contouring. The test programs we sent to United Computing supposedly do not incorporate the proper techniques for this function. United is going to revise one of these programs and send us the results. The results should be available March 29. If a problem does exist with the post-processor, the correction should be received approximately April 15, 1974.

RICHARDSON ROUTER

Problems that exist with this post-processor are as follows:

- (1) Erroneous output in certain cases of points at the start of a circle.
- (2) Post-processor won't output circular motion along an inclined plane in circular interpolation mode (outputs in short linear moves).