

MODEL SHOP WORK LOAD AS of 4-15-74

<u>WORK ON HAND</u>	<u>DATE REQ</u>	<u>EST. COMP.</u>	<u>DAYS BEHIND</u>
<u>3200</u> Mono Blocks	4-22	4-19	
Trigger Guard	4-17	4-17	
<u>742X</u> Bolt Retaining Pin	4-23	4-22	
Bolt Carrier - ALT.	4-24	4-22	
Bolt Heads - ALT.	4-22	4-22	
<u>1100X</u> Action Spring	4-16	4-16	
Trigger Plate Ret. SPRING	4-18	4-18	
Trigger Blank + Fixture	4-22	4-22	
Shell cut-off latch Spring	5-15	4-22	
Trigger Plate Ret. Plunger	6-3	4-19	
Port Cover	6-3	4-25	
FEED Latch	6-3	4-25	
<u>TRAP JOB</u> Cocking Lever Handle	4-17	4-18	
<u>700</u> Trigger Side Plate	4-16	4-16	
<u>1100 12ga.</u> Action Bars	4-15	4-17	
Fore End Support	4-29	5-10	9
<u>Bullet Job</u> Slide + JACKET Stop	4-19	4-18	

MODEL SHOP WORK LOAD AS of 4-15-74

<u>WORK IN PROCESS</u>	<u>DATE REQ</u>	<u>EST COMP</u>	<u>DAY: BEHIN</u>
<u>3200</u> Ejectors	4-15	4-16	1
<u>1100X</u> Top Lock Lever	—	4-15	
Frames	—	4-17	
Action Spring Tube + Nut		4-15	
Vent Rib		4-17	
Barrel Extensions		5-1	
Sear		4-18	
Misc. Screws + Pins		4-15	
<u>742X</u> A.S.I.W. Assembly		4-15	

R. Rockwell - VACATION
E. Uoteler - VACATION