

REMINGTON ARMS COMPANY, INC.

Field Service
Bpt., Conn.

RECOMMENDED

GUNSMITH CALL REPORT

OO: Gene Porter

cm LONG'S GUN SHOP Reporter P. W. Thompson Date 4/19/71

Address 3215 7th St. Lewiston, Idaho Zip 83504

Street City State

Type of Business Repairing Dealer () Large () Small ()

Persons Interviewed Mr. Edward Long Position Gunsmith

GENERAL DISCUSSION

Mr. Long is employed as a tool and die maker at Spear and operates his shop evenings and week ends. At this time he has been advised by his doctor to let up on his activities and will close his shop temporarily except for his club members and friends. Items that he mentioned were: a M700 in which had a blown case in the chamber--after removing it and testing with Horn & Spear X case functioned properly although in testing with JCI ammo did get a couple of blown cases again and stated I've come to the conclusion this is just to hot for this gun. Also a fairly new M700 in which the customer stated went off while closing the bolt--Ed. stated that I checked this gun out good and you just could not make it go off unless you pulled the trigger. Adding I service all the guns at the plant we use in our testing--most of them are yours and we hardly ever have any trouble. I suggested if this trouble is encountered again we would like to have the gun returned to us for checking--this he assured me he would do. Showed me a new Spear 38 S&W cartridge with a plastic cup holding 9 shot --the cup part extends approx. 3/8" out from the case as bullet and about the same length within. Stated that these are just hitting the head of and at present have a large bottleneck for them. Will remove this shop from our record. Listing altough I was assured he would handle any rem. work that was brought to him.