



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS
BRIDGEPORT, CONNECTICUT 06602

TELEPHONE
203-333-1112

November 3, 1978

RECEIVED

TO OUR FIREARMS DISTRIBUTORS

NOV - 7 1978

SUBJECT: BULLETIN - RIFLE RECALL

PRODUCT SERVICE
BRIDGEPORT

Gentlemen:

Attached is a copy of a News Release related to the Recall of one model of our center fire rifles, and our one handgun.

Model Being Recalled

- All Remington-Brand Model 600 Bolt Action Center Fire Rifles
- All Remington-Brand Model 660 Bolt Action Center Fire Rifles
- Any Mohawk-Brand Model 600 Bolt Action Center Fire Rifle except those with a serial number starting with an "A"
- Any Remington-Brand XP-100 Center Fire handgun with a serial number less than #7,507,984, except those with the prefix "A" or "B" before the number.

Dates of Manufacture

Prior to February, 1975.

How Recall is Being Handled

Consumers having guns covered by the recall should be told that Remington recommends that prior to any further usage of their guns they be inspected and modified as required. This will be done at no charge by participating gunsmiths around the country. Consumers may call one of the following numbers for the name of the nearest participating gunsmith.

- All States Except Georgia 1-800-241-8444 - Operator 61
- Georgia Only 1-800-282-1333 - Operator 61

PLAINTIFFS
EXHIBIT
M-10

FIREARMS DISTRIBUTORS

-2-

November 3, 1978

If the location is not convenient to personally deliver the gun, the consumer may send the gun collect to the gunsmith and have it returned prepaid.

What Distributors Can Do

We suggest you check your gun inventories to be absolutely sure none of these recall rifles remain in your stock. Also, in a short time we will be giving you further information which will help you to determine the dealers to whom you may have shipped some of these rifles.

What Your Dealers Can Do

Dealers should look through their files to determine shooters to whom the guns were sold. Shooters should then be contacted and told to call the toll-free number for procedures. Also, dealers should check their inventories to be absolutely sure they don't have any of the rifles remaining.

Presently we are combing our files to send you information we will have available on shipments we have made to you of this model. Retrieval of this information in such large quantities is time consuming. If you have any questions for us, please call our Mr. Jack Chisnall at our special WATS ACTION LINE 1-800-243-9275 (inside Connecticut 1-800-972-9379) or write him at the address shown on page 1 of this letter.

Thanks again for your cooperation in handling this recall. Additional information will be sent to you as available, together with a copy of a letter to the dealers which is now being prepared.

Sincerely,

E. J. Conroy
E. J. Conroy
Director of Sales

EJC/o

attachment

- ① Name of Gurnsmith should be typed in both blanks.
- ② "Vice President and Director of Marketing" should be typed in under J. G. Williams signature.
- ③ Date should be filled in as of date you mail out.

J. G. Williams

RECEIVED
NOV - 3 1978
PRODUCT SERVICE
BRIDGEPORT