

*Status?*

**DON'T SAY IT — WRITE IT**

G-88

To J. P. LINDE — F. E. MARTIN  
From A. A. HUGICK

*Fickett*  
Date May 12, 1977

Two years ago the XP-100 bolt plug and safety assembly designs were reviewed due to pending impact test of exposed hammer — striker assemblies. The safety has been modified with thumb piece material change — BUT — bolt plug changes have not been implemented. Abuse of the M/600 bolt plug for eliminating an exposed striker should be implemented as soon as possible.

AAH:bd  
Measurement/Test Lab  
Illion Research Division

Copies to: C. B. Workman  
File

**DON'T BE SORRY — BE SAFE**