

Chu

for Figure 6-9. The given for indirect measurement
 .018". Put this measurement on the Test
 Procedure Sheet under Given for Indirect.

11. Repeat steps 3 through 10 two more times ^{you should have}
 at the end of the third trial, ~~the~~ ^{you should have}
 this given for indirect measurement on the Test Procedure
 Sheet. (Refer to Appendix B).

12. Remington has set standards for the given for
 indirect measurement of the main measurement
 which fall within the standards, note this
 in the Test Procedure Sheet and note
 and submission. The standards can be found
 in the manual Technical Drawing - the
 Drafting Cabinet.

in each
 drawing
 manufactured
 by Remington