

REV. 6-58

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

REPORT

CC/H. CHASE

J. P. Linde

xc: E. F. Barrett
R. A. Partnoy
J. G. Williams
E. Hooton, Jr.
Product Safety
Subcommittee File

Copy to Dennis Linde

PE + e must give you written
procedures and verbal instructions
plus inspection of modifications.

Bridgeport, Connecticut
July 19, 1979

HKB


R. L. HALL 7/20

7-23-79

REPAIR OF MODEL 721-722 TRIGGER ASSEMBLIES

Members of the Product Safety Subcommittee have approved the procedures recommended by Research and Development for repairing Models 721 and 722 rifles by replacing the trigger assembly with a modified Model 700 trigger assembly.

Details of the repair procedure are given in John Linde's May 21, 1979, letter to you. Copies of this letter and other relevant correspondence, including the note with Subcommittee approvals, are attached. Copies are also retained in the Subcommittee's file.


B. K. Daubenspeck
Product Safety Subcommittee
Secretary

BKD/cas