	•				
REV. 8-58					
REMINGTON	ARMS	COMPANY, IN	C.		
INTER-DEPARTMENTAL CORRESPONDENCE					

Remington AUMAP

		·				•	
•				•			
					•		
	·						

September 21, 1979

17

21 :

то:	E. G. Larson
FROM :	R. G. Sherman
SUBJECT:	RECALL REPAIR STATUS

TOTAL REPAIRS MADE BY ILION THROUGH 7/14/79

NODEL XP-100 NODEL 600-660	- 1,506 <u>- 879</u> Al. 2,385
TOTAL REPAIRS MADE BY CANADA	479
TOTAL REPAIRS BY FIELD SERVICE STATIONS THROUGH 9/	18/79 17,512
REPAIRS MADE BY NYCPD (Not-included in Accounting's APV's)	313
REPAIRS MADE AT THE BRIDGEPORT GUN SHOP	12 .
NUMBER OF REPAIRS REPAIRS MODE ON T NUMBER OF ENTERTIME NOT PAID AS OF 9/18/79 TOTAL DOCUMENTED REPAIRS TO DATE	20,701 <u>193</u> 20,894
(Not Included in Accounting's APV's)	Ħ
TOTAL TRICGERS PRODUCED BY ILION TO DATE	23,752
TOTAL TRIGGERS SHIPPED BY ILION	23,722
TOTAL TRICCERS ON HAND IN 11.10N	30

· 25

E. G. Larson

September 21, 1979

30 units

193

ILION TRIGGER INVENTORY 9/20/79

UNPAID INVOICES OUTSTANDING

The amount of additional recall repairs that will be generated as a result of our latest 140,000 unit ATF mailing would be only sheer speculation at this point. However, I believe that we would be safe in saying that between now and the end of 1979 the repairs performed in the field would fall between 1,500 and 2,000 units.

-2-

Although there would be a certain amount of time and additional expense involved, we might consider contacting each one of our service stations requesting:

- 1. The number of fire control units on hand.
- 2. The number of Model 600-660 rifles to be repaired.
- 3. The best estimate of what they would expect to repair in possibly
- the next 3 months.

This could be accomplished with a letter containing a return self-addressed envelope or actually making the phone calls from our department down here. If Ilion is seriously concerned about the possibility of a fire control overrun that may not be utilized, possibly this would give them the most accurate numbers to base our future trigger assembly production on.

Best regards man

' R. G. Sherman

RCS/ac

We are doing this.

R2508566