

SPEED MESSAGE

TO REMINGTON ARMS COMPANY
Arms Service Division
Ilion
New York 13357

FROM Snappy ServiSenter

1400 HIWAY 2 EAST — PHONE 406-257-7525

KALISPELL, MONTANA 59901

Attn: Jim Stekl

SUBJECT Warranty Repair of Remington Model 600, serial # 71789

DATE November 19, 1979

Dear Mr. Stekl:


Please find enclosed subject firearm which I am returning for my customer, Mr. Michael Harvey of Kalispell, Montana. Mr. Harvey returned this firearm to me recently, and asked that I return the firearm to you for inspection and repair of the hammer, sear, and safety assembly. Mr. Harvey feels that this firearm is one of those to which the Model 600 recall applies. I have confirmed this.

Mr. Harvey had a bad experience with this firearm, when it accidentally discharged as he was unloading the rifle. I have enclosed a note from Mr. Harvey.

Please repair this firearm under warranty, thoroughly function check and test fire, and return at your very earliest convenience to us at the above address.

Thankyou for your attention to this matter.

Sincerely,



W. J. LUPTON

SIGNED